Unwatch

Part 2: Top & Bottom of the Plenum Box Added »

Search LumberJocks.com

Chop Saw Dust Hood #1: Top, middle rail, and back glued in place Blog entry by BlankMan posted 11-25-2009 02:34 AM **35832** reads 41 times favorited **14** comments

Part 1 of <u>Chop Saw Dust Hood</u> series

BlankMan home | projects | blog 1491 posts in 4616 days **VIEW BLOG ARCHIVE** 🖸 RSS FEED 🔕 B 📆 ... By subscribing to the RSS feed you will be notified when new entries are posted on this blog.

no previous part

making the old hood too small to cover the area needed. Been without one for about a year because I also picked up the Delta 12" RAS and had to redo the bench for that to fit also. So I wasn't about to build a hood until both the RAS and miter saw were firmly mounted in place. The hood is 28-1/2" wide and ~19" tall made out of Baltic birch plywood. It's wide enough to cover capturing the sawdust even when the saw is at 45 degrees in either direction. If all goes well I'm hoping to have it done by the weekend. Then I'll vacuum up all the sawdust that has accumulated behind the bench one last time and put it in place. Front view with the top and middle divider rail glued and clamped in place.

Well Sunday I finally got around to start building a new dust collection hood for behind my new miter saw. I

had one behind my old miter saw but this new saw is wider and I had to redo the bench for it to fit thus


Entry tags/keywords


project_progress miter_saw Recent Entries Workshop Lighting Upgrade - 05-05-2012 03:19 PM

Dust Collection Air Flow Probes -04-01-2012 08:48 PM <u>Installed a Byrd Shelix</u> Cutterhead in my DeWalt DW735 <u>Planer</u> - 06-14-2011 11:26 AM









Hi BlankMan. Nice hood. I know what you mean about the dust from the miter saw. Mine was the dirtiest tool in the shop. I always had to sweep up about 4" of dust behind it. I was going to post mine too when I get

-- "Those who would give up essential Liberty, to purchase a little temporary Safety, deserve neither Liberty nor

oldartie, yeah, thanks for the report. Went to the dark side, switched to AT&T as a internet provider over the weekend, they're interpretation of static IP configuration and no ports blocked differs from the definition that

Quote

Latest activity

11-10-2021 06:00 PM

11-10-2021 05:51 PM

Looks like that will work, chop saw is the hardest tool to collect dust for, there is always all kinds of it behind

-- Mert,Oshkosh WI,

some pictures.

Thanks!

my saw.

Nice work Curt. I need to make one for my saw. Patrick – Milwaukee

Great Job!!!!!!!!! Necessity is the mother of invention. -- Jim Jakosh.....Practical Wood Products......Learn something new every day!! Variety is the Spice of Life!!

Thanks for the inspiration!

The picture links are no longer active. I'd love to see them. I watched the video of the dust collector working, and I'd like to see more.

Safety." Benjamin Franklin -- Jesus is the ONLY reason for ANY season.

the rest of the world uses. Pretty much expected this was going to happen based on previous dealings with Ameritch, SBC, and now AT&T, the name may change but their core operation hasn't, they are challenged to #7 posted 04-19-2010 02:01 PM no end to get it right, very seldom the first time... Yesterday most things were working, today they're not, there's always tomorrow I guess. Last night they fixed one thing, looks like they broke two others (that I am aware of) that were working, one being port 80 ergo no access to the web server hence no pictures...

-- -Curt, Milwaukee, WI BlankMan Well, I think the picture problems have been resolved hopefully for good. If they disappear again I'd definitely like to hear. home | projects | blog 1491 posts in 4616 days -- - Curt, Milwaukee, WI #8 posted 04-21-2010 04:32 PM upnorth What happened to the pictures? Not very usefull without pictures... home | projects | blog 1 post in 3868 days

Where do you attach the suction for the hood? I did not see it in any pictures.

Check back every so often, working on resolving this...

#9 posted 04-09-2011 09:46 AM **Simatai** home | projects | blog

BlankMan

brad53

#12 posted 01-06-2012 06:50 PM

BlankMan

#13 posted 01-06-2012 08:07 PM

Duke407

#14 posted 11-10-2021 04:48 PM

home | projects | blog

1 post in 78 minutes

1 post in 3595 days

best for you but I'll measure it if you like. Make it big to cover the swing of the saw and high as you can. I had to cut out it's top so to clear the saw and allow it to swivel because I couldn't go taller then the saw due of the shelf. The slope of the back is 15 degrees I think so that the sawdust would hit it and angle down towards the suction. -- -Curt, Milwaukee, WI Quote

Thanks. The dimensions were governed strictly by where it had to fit. If you look at Part 6 of the blog you can see it had to fit between two machines and under a shelf. So I don't know that my dimensions would be the

Do have a rough set of dimensions of the side piece? Trying to puzzle out a few things but my spatial sense is

Adapting your design to a DW735 and my vent system comes from below. Trying to determine the best fix fro

Brad, there's a picture in Part 3 of this blog showing the port glued in place (the black thing) and of it connected in Part 7.

not so good. 3

that as well.. It is the best i have seen

-- - Curt, Milwaukee, WI Quote I cannot see any pics. Can you possibly send me the pics to my email.account at: cid407@gmail.com

BlankMan home | projects | blog 1491 posts in 4616 days

Have your say... + View the posting rules PREVIEW **show formatting reference** | pictures & videos friendly

Forum Topics RSS

Mutt_and_leff.	Roman - THE BOOTMAN	11-10-2021 05:48 PM	never checked
Gift_of_a_Lifetime	<u>DevinT</u>	11-10-2021 05:47 PM	never checked
How_should_I_go_about_repairing_these_pool_table_legs?	<u>BeerBrewer</u>	11-10-2021 05:44 PM	never checked
QI_Charger_for_floating_bedside_tables.	CvrdNDust	11-10-2021 05:41 PM	never checked
Off-topic content. Click to see the post.	<u>stevejack</u>	11-10-2021 05:26 PM	never checked
Off-topic content. Click to see the post.	woodbutcherbynight	11-10-2021 05:13 PM	never checked
Question about veneering archtop guitars	<u>Tony1212</u>	11-10-2021 05:09 PM	never checked
F1_Race_Car_Qut_Of_Walnut_And_Maple	<u>RickSanchez</u>	11-10-2021 05:09 PM	never checked
Home Projects Blogs Videos Reviews Forums Tags Old Classes Who's Online	Pulse eMag Site Blog	Site Rules Help Contact Us Adve	rtise
©2021 Verticalscope Inc. All Rights Reserved. Terms of Service Copyright Privacy Policy			

Site Blog Entries RSS

Author

Keebler1

Don W

DISCLAIMER: Any posts on LJ are posted by individuals acting in their own right and do not necessarily reflect the views of LJ. LJ will not be held liable for the actions of any user.

Advertise with us

Front view of the back glued and clamped into place.

Side view of the back glued and clamped into place.

a1Jim home | projects | blog -- https://www.artisticwoodstudio.com/videos 118286 posts in 4840 days #1 posted 11-25-2009 02:55 AM

home | projects | blog 21 posts in 4376 days #3 posted 11-25-2009 10:31 AM

Jim Jakosh

gmerteng

#2 posted 11-25-2009 07:14 AM

home | projects | blog 122 posts in 4376 days

home | projects | blog 26901 posts in 4369 days #4 posted 11-25-2009 11:17 AM lightweightladylefty home | projects | blog

3661 posts in 4976 days

oldartie

BlankMan

#5 posted 11-26-2009 01:00 AM home | projects | blog 1 post in 4223 days #6 posted 04-19-2010 01:43 PM

<u>home</u> | <u>projects</u> | <u>blog</u> 1491 posts in 4616 days

5 posts in 3663 days #10 posted 10-31-2011 12:18 PM home | projects | blog 1491 posts in 4616 days #11 posted 10-31-2011 10:54 PM

home | projects | blog home | projects | blog 1491 posts in 4616 days

All Posts RSS

Projects RSS

LumberJocks Pulse - all activity, active in last 30 days F Shop tool Swap 2021

F Show the restoration before and after. P Mutt_and_Jeff. R Gift of a Lifetime

Post this comment

F Off-topic content. Click to see the F Question about veneering archto P F1 Race Car Out Of Walnut And N

Blog Entries RSS

I need more room Open mini-browser Open mini-browser

Reviews RSS

Go to Pulse page »

never checked

New comments or replies

7713 new in last 3529 days

since you last checked